

HGFA Airwaves May, 2012

## Alert Service Bulletin - ROTAX / fuel hose

Alert Service Bulletin for Rotax ASB-912-061 UL Mandatory and Urgent Part Replacement Before Next Flight

 Replacement of the pressure side fuel hose at fuel pump part #893114 for ROTAX Type 912 (Series)

Due to variations in the manufacturing of the fuel hose, rubber particles may become detached. These particles can interfere or suppress the fuel mixture in the carburetor. This disturbance in the fuel mixture may lead to rough engine operation, engine misfire and can cause an engine shut down...

Read the full Alert Service Bulletin here.

## About 'Airwaves'

Airwaves is intended to communicate pertinent notices in-between the printed magazine editions.

If anyone has any suggestions or comments about 'Airwaves' then please send them through to:  $\underline{secretary@hgfa.asn.au}$ .

### Feedback

Questions and or feedback regarding HGFA Operations or Management are welcome! Please feel free to email the HGFA Committee (committee@hgfa.asn.au).

#### Sincerely,

The HGFA

Join Our Mailing List!

#### **HGFA**



**HGFA** Website

#### **State Associations**

<u>ACT</u>

NSW

QLD

SA

<u>Tas</u>

<u>WA</u>

# VIC Moyes



Visit Our Sponsor

## **High Adventure**



#### **Icaro Helmets**



Visit Our Sponsor

